

	<b>VANDAL RESISTANCE</b>	<b>WEATHER RESISTANCE</b>	<b>UV RESISTANCE</b>	<b>HEAT DISSIPATION</b>	<b>VENTILATION</b>	<b>AESTHETICS</b>	<b>CONVENIENCE OF USE</b>
<b>Stainless Steel</b>	High Tensile Strength  Three-point Locking System  Concealed Padlock  Cam Style Lock Provided  Graffiti Easily Removed  Scratch Resistant Finish	Impervious To Corrosion  Rain Gutter Drainage Channel  Teardrop Shaped, Hollow Center, Water-tight, Thermoplastic Door Seal  Enhances Lightning Protection  UL Listed  NEMA 3R Rated	Impervious To UV Deterioration	High Reflective Value, Lowest Internal Temperatures Minimizes Heat Affect On Electronics	Filtered Crossflow Ventilation Minimizes Internal Condensation Buildup, Allows Rapid Heat Dissipation, Filters Dust, Dirt & Insects  Fan Kit Available	Chameleon Effect On The Natural Brushed Stainless Steel Finish Blends With It's Environment And Provides An Unobtrusive Quality	Installation Template Guides Placement Of Low & High Voltage Conduit And Anchor Bolts  Removable Predrilled Backboard Provides For Easy Installation  Accepts QuickPad
<b>Carbon Steel</b>	Three-point Locking System  Exposed Padlock  No Cam Style Lock  Graffiti Removal Damages Finish Requiring Repainting  Finish Easily Scratched	Subject To Corrosion Requiring Continual Maintenance  Rain Gutter Drainage Channel  Enhances Lightning Protection  Door Gasket	Finish Subject To Fading	Poor Reflective Value Unless Very Light Color Used	Non-crossflow Louvered Door	Painted Finish Difficult To Match To Natural Environment  Subject To Fading & Rusting	Mounting Platform Set In Concrete
<b>Plastic/ Fiberglass</b>	Three-point Locking System  Cam Style Lock Only No Padlock Capability  Graffiti Removal Damages Finish  Finish Easily Scratched—Difficult To Repair	Resistant To Corrosion  No Door Seal	Finish Subject To Fading  Permanent Damage To Material	Very Slow Heat Dissipation  Retained Heat Will Damage Electronic Components	No Ventilation Contributes To Condensation Buildup And Heat Retention	Color Difficult To Match To Natural Environment  Subject To Fading, Scratching  Difficult To Repaint	